


March 2021 (3rd April 2021)

Note; E/B, W/B, S/B, N/B













Ref	Location	Comment
		Reported to NCC ref; ENQ900182100, ENQ900182101 and ENQ900182102.
		Otherwise, no issues observed (3 rd April)
Brow of the Hill	Between Leziate Village Hall and Junction with Station Rd / Sandy Lane	No Issues observed (3 rd April)
	Between Junction with Brow of the Hill / Sandy Lane and Holt House Lane	There is erosion of the S/B nearside road edge between Nr 1 Station Rd and its intersection with Sandy Lane.
		Report to NCC ref; ENQ900179210; NCC Response;
Station Rd		No action has been taken at this time but we will continue to monitor the problem -We have assessed that the defect does not currently meet our intervention criteria. We will continue to monitor as part of normal scheduled inspections.
		Otherwise, no Issues observed (3 rd April)
	Between Junction with Holt House Lane and Parish Boundary to the south	Some kerb offlets blocked with detritus.
Station Rd		Significant improvements to the road approaching the level crossing after highway surfacing works during recent closure
		Otherwise, no issues observed (3 rd April)
		Vegetation obscuring School warning sign
	Between junction with B1145 and Holt House Lane	Report to NCC ref; ENQ900179211; NCC Response;
East Winch Rd		We have inspected and are going to resolve the problem - After investigation we have confirmed action is required. Defects are scheduled for repair depending on the nature of the defect and work needed but on average can take approximately 6 weeks
		There is some emerging damage to road edges following winter freeze/thaw period see photos at end
		Otherwise, no Issues observed (3 rd April)
East Winch Rd	Between junction with Holt House Lane and Church Lane	Vegetation was observed obscuring W/B speed limit sign and the same sign is leaning away from road.
		OK at present, but will need cutting back in the spring. Report to NCC ref; ENQ900179215;






Ref	Location	Comment
		The damaged W/B chevron warning sign just to the east of the junction with Holt House Lane (south of Nr 83 East Winch Rd) is still un-repaired
		Otherwise, no Issues observed (3 rd April)
East Winch	Between junction with Church Lane and Parish Boundary to the South at	There is some emerging damage to road edges following winter freeze/thaw period
Rd	East Winch	Otherwise, no Issues observed (3 rd April)
	Between junction with B1145 and Parish Boundary to the north at Pott Row	Gully silted up outside access to Pightle Farm
		Report to NCC ref; ENQ900179221; NCC Response;
Leziate Drove		A site visit has been carried out and issue has been resolved.
		No it hasn't. Blocked gully reported again to NCC - ref; ENQ900182097 - photo attached at end of report.
		Otherwise, no Issues observed (3 rd April)
	Between junction with B1145 and Leziate RB25 to the Church	Road sign has been uprooted following impact by vehicle. Now leaning up against bus-stop -
		Report to NCC ref; ENQ900179224; NCC Response;
		A site visit has been carried out and issue has been resolved.
		No it hasn't. Damage to road-sign has been reported again to NCC - ref; ENQ900182098 - photo attached at end of report.
Church Lane		Freeze-thaw damage to edge of road outside nr 20 reported to NCC - ref ENQ900182103 and
		One gully partially silted up opposite entrance to Ashwicken Hall and road damaged around it reported to NCC - ref ENQ900182104 and
		opposite Hadleigh Fm livery yard reported to NCC - ref ENQ900182105
		Photos at end of report
		Otherwise, no Issues observed (3 rd April)
Church Lane	Between Leziate RB25 to the Church and the Sewage Works	A previous repair of approx. 50m of the edge of Church Lane has failed due to passage of vehicles too large for the capacity of the road.
		Report to NCC ref; ENQ900179226; NCC Response;






Ref	Location	Comment
		We could not find the problem so have not taken any action at this time - It is possible that the defect has already been repaired. If you know the defect is still present please log again including any additional location detail.
		This has been reported to NCC again under Report ref ENQ900182099 – photos at end
		Flytipped rubbish on corner of Church Lane near to Sewage works.
		Otherwise, no Issues observed (3 rd April)
		Pothole in the W/B near-side wheel track has been increasing in size during recent freeze-thaw conditions
		(near to solitary oak on the northern side of the road).
	Potygon the Course	Report to NCC ref; ENQ900179242; NCC Response;
Church Lane	Between the Sewage Works and junction with East Winch Rd	We have inspected and are going to resolve the problem - After investigation we have confirmed action is required. Defects are scheduled for repair depending on the nature of the defect and work needed but on average can take approximately 6 weeks.
		No action has been taken yet.
		Otherwise, no Issues observed (3 rd April)
Fen Lane	Between junction with B1145 and Leziate RB15 to Brands Wood	No Issues observed (3 rd April)
Well Hall Lane	Between junction with B1145 / Fen Lane and Parish Boundary to the east (Gayton)	No Issues observed (3 rd April)
	Between Junction with Station Rd and limit of surfaced road	Carriageway damage in middle of road
Holt House Lane		Report to NCC ref; ENQ900179244; NCC Response;
		This problem has already been reported and action identified to resolve the issue - It is likely that the defect was identified as part of our routine scheduled inspections and already prioritised for repair.
		No action has been taken yet.





Ref	Location	Comment
		Otherwise, no Issues observed (3 rd April)
Holt House Lane	Between limit of surfaced road and RB13	Standing water in some locations Otherwise, no Issues observed (3 rd April)
		Stormwater flowing off adjacent fields is causing severe erosion of the track over circa 350m to 400m of this length. This has become progressively worse over several years which has seen a lowering of the road surface below that of adjacent ditches, exacerbating the issue. In the summer of 2020, this caused difficulty for emergency services' vehicles negotiating the highway.
Holt	Between RB13 and Field	Reports here relates to a 350m section;
House	Gateway to Wicken North / DoubleWood	Report to NCC ref; ENQ900179280; NCC Response;
Lane	Conservation area	Report to NCC ref; ENQ900179281; NCC Response;
		Report to NCC ref; ENQ900179283; NCC Response;
		No action has been taken at this time but we will continue to monitor the problem -We have assessed that the defect does not currently meet our intervention criteria. We will continue to monitor as part of normal scheduled inspections.
		Otherwise, no Issues observed (3 rd April)
	Between Field Gateway to Wicken North / DoubleWood Conservation area and East Winch Rd	Similar issues as above but this section of Holt House Lane is where the majority of the eroded material from the west has been deposited. The erosion is also causing a significant fall to be created across the track in some areas. During Stormwater conditions, the flooding is severe enough to generate a few cascade waterfalls
_		Reports here relates to a 150m section
Holt House		near to the restoration nature area entrance
Lane		Report to NCC ref; ENQ900179284; NCC Response;
		Report to NCC ref; ENQ900179288; NCC Response;
		Report to NCC ref; ENQ900179290; NCC Response;
		No action has been taken at this time but we will continue to monitor the problem -We have assessed that the defect does not currently meet our intervention criteria. We will continue to monitor as part of normal scheduled inspections.





Ref	Location	Comment
		Otherwise, no Issues observed (3rd April)


Brow of the Hill Blocked kerb drains between B1145 and Sailing Club













March 2021 (3rd April 2021)







East Winch Rd Between junction with B1145 and Holt House Lane







Leziate Drove



March 2021 (3rd April 2021)

Church Lane road name sign





Church Lane edge damage











March 2021 (3rd April 2021)







